

**SYRACUSE UNIVERSITY LIBRARY - SPECIAL COLLECTIONS  
LOCOMOTIVES AND CARS IN THE GLASS PLATE  
DELAWARE, LACKAWANNA & WESTERN RAILROAD COLLECTION**

**SECTION A - 8 X 10**

<b>Neg. No.</b>	<b>Date</b>	<b>Description</b>
28	03/13/05	Mine Car with Replaceable Wheel - Axle Sets,
29	03/13/05	Mine Car, Wescott Patent
30	03/13/05	Mine Car, Bottom View
31	03/13/05	Mine Car, Bottom View
32	03/13/05	Mine Car, Side View
33	03/13/05	Mine Car, Side View
143		Hospital Car, DL&W RR - Interior - Car #99010
144		Duplicate - #143
145		Hospital Car - DL&W RR - Exterior - Loading Victim, Car #99010.
146		Hospital Car - DL&W RR - Exterior - Loading Victim, Car #99010.
378	04/28/06	Rural Railroad Crossing - View Looking Down Track with Train
395		Excavating for New Yard at Taylor, PA -Steam Shovel - Loading Cars.
396		Excavating for New Yard at Taylor, PA -Steam Shovel - Loading Cars.
397		Excavating for New Yard at Taylor, PA -Steam Shovel - Loading Cars.
446	09/06/06	Eastern and Central New York Retail Coal Merchants Train - L.V.R.R. #1430
464-1st		DL&W Hopper Car, 40 Ton, #73453, Loaded with Coal, Full Side View
804		Bliss Colliery, Electric Mine Loco with Cars Leaving Drift
805		Bliss Colliery, Electric Mine Loco with Cars on Level
813		Mine Rescue Car, Baggage Car #758.
814		Mine Rescue Car, Baggage Car #758. Interior
815		Mine Rescue Car, Baggage Car #758. Interior
837	03/08/11	Cars on Sidings at Above Location, Rock Dump in Background
900	10/26/11	Truesdale Mine, "Concrete City", Concrete Car and Pouring into Forms
1137		Conveyor Type Equipment for Loading Mined Coal into Mine Cars
1242		Pair of Oxen Pulling Mine Car
1376	10/02/17	Truesdale Colliery, 15 Ton Electric Locomotive, Outside.
1377	10/02/17	Truesdale Colliery, 15 Ton Electric Locomotive, Outside.

**SECTION B - 8 X 10**

<b>Neg. No.</b>	<b>Date</b>	<b>Description</b>
35		Nay Aug Tunnel Entrance and Work Train
36		Nay Aug Tunnel Entrance and Work Train
39	11/30/06	Retaining Wall-East of Scranton Station part view Engine 630
87		Side rods and drivers, locomotive 885
88		Side rods and drivers, locomotive 885
111		Engine 1003 after wreck, left side
112		Engine 1003 after wreck, right side
118		Boiler of Engine 408 at Scranton Shops
123	09/17/07	Construction train on fill
124	09/17/07	Construction train in cut
144		Scranton station construction and misc. freight cars
147		Scranton station construction and misc. freight cars
148		Scranton station construction and misc. freight cars
182		Box Car 4084 Built 1907 Also negative 182A
183		Box Car 32608 Built 1907
184		Box Car Interior
185		Box Car Interior
195		Engine 834 after wreck
196		Engine 586 after wreck
258		Ice Car 5990 built 1908
259		Ice Car 5990 Interior
320	01/23/09	Broken locomotive axle
339	03/10/09	Locomotive Tender Truck
340	03/10/09	Locomotive Tender Truck
341	03/10/09	Broken Locomotive Axle
370		Inspection Engine "B" left side
784		Rear of inspection train. Location (?)
786		Engine #1016 and Train Dover, NJ
786		Engine #980 and Train Dover, NJ
786		Engine #950 and Train Dover, NJ
826		First aid class in safety car
827		First aid class in safety car
828		First aid class in safety car
829		First aid class in safety car
830		First aid class in safety car
831		First aid class in safety car
832		First aid class in safety car
833		Wreck scene
834		Wreck scene
838		Wreck scene
839		Wreck scene
840		Wreck scene

<b>Neg. No.</b>	<b>Date</b>	<b>Description</b>
851		Engine 1034 and train - Scranton
852	05/09/12	Toppling old stack - Scranton shops
853	05/09/12	Toppling old stack - Scranton shops
854	05/09/12	Close-up of stack - Scranton shops
1002		Nicholson Cut - wreck of construction train
1013		Construction train
1077		Front view Engine 34 (0-6-0)
1078		3/4 view Engine 34 (0-6-0)
1209		Port Morris tower and passenger train
1250		Donkey engine at 1 mile west from Clarks Summit
1294		Work train
1295		Work train
1296		Work train
1297		Back head of Locomotive
1298		Back head of Locomotive (better)
1299		Back head of Locomotive (better) #398
1300		Back head of Locomotive 750
1301		Back head of Locomotive 1105
1302		Back head of Locomotive 9
1396		5 Engine coal train - west of Scranton
1399		5 Engine coal train - west of Scranton
1429	05/06/13	Smoke Box Locomotive # 782
1442	May 1913	Locomotive # 156 at Scranton 0-8-0

**SECTION C**

<b>Neg. No.</b>	<b>Date</b>	<b>Description</b>
287	08/20/08	Auto involved in accident
295	10/02/08	View from road of freight cars through orchard
296	10/02/08	Freight car near crossing - view from road
297	10/02/08	Freight car near crossing - view from road
298	10/02/08	Freight car near crossing - view from road
299	10/02/08	View down track from road crossing
300	10/02/08	View down road from railroad crossing (wrecked carriage)
304	10/06/08	Milk car #1603 (M&E division)
305	10/06/08	Milk car #1603 (M&E division) - end view
306	10/06/08	Milk car #1603 (M&E division) - end and corner view
307	10/06/08	Milk car #1603 (M&E division) - view from opposite end of photo C-304
369	02/05/09	Engine #425 - Corner of wooden pilot beam
370	02/05/09	Engine #425 - Corner of wooden pilot beam
371	02/05/09	Engine #425 - front view
375	02/17/09	Carriage damaged in accident
415	04/14/09	Northumberland, PA - crossing with street car - view up railroad to crossing
416	04/14/09	Northumberland, PA - crossing with street car
431	05/28/09	Siding for wood loading - main line - signal # 1007, with Gondola
432	05/28/09	Siding for wood loading - main line - signal # 1007, with Gondola
433	05/28/09	Siding for wood loading - main line - signal # 1007
451	06/22/09	Mount Pocono, PA - Engine 871 - showing close clearance at freight platform roof
452	06/22/09	Mount Pocono, PA - Engine 871 - showing close clearance at freight platform roof
453	06/22/09	Mount Pocono, PA - Engine 871 - showing close clearance at freight platform roof
456	06/30/09	Mount Pocono, PA - Engine 871 - showing close clearance at freight platform roof
457	06/30/09	Mount Pocono, PA - Engine 871 - showing close clearance at freight platform roof
458	06/30/09	Mount Pocono, PA - Engine 871 - showing close clearance at freight platform roof
459	06/30/09	Mount Pocono, PA - Engine 871 - showing close clearance at freight platform roof
460	06/30/09	Mount Pocono, PA - Engine 871 - showing close clearance at freight platform roof
461	06/30/09	Mount Pocono, PA - Engine 871 - showing close clearance at freight platform roof
462	06/30/09	Mount Pocono, PA - Engine 871 - showing close clearance at freight platform roof
463	06/30/09	Mount Pocono, PA - Engine 871 - showing close clearance at freight platform roof

<b>Neg. No.</b>	<b>Date</b>	<b>Description</b>
464	06/30/09	Mount Pocono, PA - Engine 871 - side view at freight platform
465	06/30/09	Mount Pocono, PA - Engine 871 - showing close clearance at freight platform roof
466	06/30/09	Mount Pocono, PA - Engine 871 - showing close clearance at freight platform roof
472	07/08/09	Kingston, PA - midway between Union and Bennett Streets - accident scene
473	07/08/09	Kingston, PA - midway between Union and Bennett Streets - accident scene
474	07/08/09	Kingston, PA - midway between Union and Bennett Streets - accident scene
488	07/26/09	Kingston, PA - accident scene west of John Street crossing - side view roadbed
489	07/26/09	Kingston, PA - accident scene west of John Street crossing - side view roadbed
490	07/26/09	Kingston, PA - accident scene west of John Street crossing - westbound view
491	07/26/09	Kingston, PA - accident scene west of John Street crossing - westbound view
492	07/26/09	Kingston, PA - accident scene west of John Street crossing - westbound view up roadbed
493	07/26/09	Kingston, PA - unprotected road crossing near John Street - general view
494	07/26/09	Kingston, PA - accident scene west of John Street crossing - eastbound view up roadbed
509	09/23/09	Rural road crossing view from cut with crossing, reverse curve and 3 arch stone bridge double track (also C288-293)
510	09/23/09	Rural road crossing view from crossing down track
511	09/23/09	Same as C-509, with passenger train - crossing no. 174
641	04/14/10	Crossing with Scranton Railway Co. - C-611-20; overall with loco and cars and crowd
642	04/14/10	Crossing with Scranton Railway Co. - C-611-20; overall with loco and cars and crowd
663	05/23/10	View - 4 track line, with loco on inside track and inside of curve
664	05/23/10	View - 4 track line, with loco on inside track and inside of curve, men in yard
665	05/23/10	View - 4 track line, with engine #854 on inside track, and adjacent house and yard
666	05/24/10	Couplings - 2 freight cars coupled - close-up - hopper and gondola cars
667	05/24/10	Couplings - 2 freight cars coupled - close-up - hopper and gondola cars
668	05/24/10	Couplings - 2 freight cars coupled - close-up - hopper and gondola cars
669	05/24/10	Couplings - 2 freight cars coupled - close-up - hopper and gondola cars
670	05/24/10	Couplings - 2 freight cars coupled - close-up - hopper and gondola cars
671	05/24/10	Hopper car #69992 - end view
672	05/24/10	Gondola car #70308 - end view
673	05/27/10	Engine #976
674	05/27/10	Engine #976 - front detail view - coupler, pilot, pilot beam, etc.
675	05/27/10	Engine #976 - bottom corner of firebox and air reservoir
676	05/27/10	Engine #976 - close-up air reservoir
677	06/04/10	Engine 50 - close clearance on wayside building
678	06/04/10	Engine 50 - close clearance on wayside building
679	06/04/10	Engine 50 - close clearance on wayside building - close-up
680	06/04/10	Engine 50 - close clearance on wayside building - close-up

<b>Neg. No.</b>	<b>Date</b>	<b>Description</b>
683	06/07/10	Engine #1031 - engine only
684	06/07/10	Engine #1031 - 3/4 view from below
685	06/07/10	Engine #1031 - front view
692	06/21/10	Hopper #44164 - wood under repair - one truck out, end of body on ground
693	06/21/10	Hopper #44164 - wood under repair - one truck out, end of body on ground
694	06/21/10	Hopper #44164 - wood under repair - body on 2 jacks
695	06/21/10	Hopper #44164 - wood under repair - with 2 wood horses
736	08/11/10	Scranton, PA - Railing/locomotive clearance on bridge over Washington Avenue (lower level - freight tracks)
738	08/11/10	Scranton, PA - railing/locomotive clearance on bridge over Washington Avenue
753	09/16/10	Close clearance - locomotive/stone water tank base
754	09/16/10	Close clearance - locomotive/stone water tank base
772	09/27/10	Single track bridge on curve - with corn field - with local passenger train C.A. Durr Packing Property
781	09/30/10	DL&W Boxcar #37288 - corner
782	09/30/10	DL&W Boxcar #37288 - bottom corner at step
783	09/30/10	DL&W Boxcar #37288 - side view
793	10/20/10	Clearance - cars/fence on siding
794	11/11/10	Locomotive #1016 - fire screen in smokebox
857	03/08/11	Creamery - brick - road crossing, view of track - milk car in siding
858	03/08/11	Creamery - brick - road crossing, view of track - milk car in siding
864	03/14/11	Pen Argyl, PA - temporary track near station - with derailed tender and Gondola - #419
867	03/14/11	Pen Argyl, PA - derailed tender, L&NE and wooden hopper #419
868	03/14/11	Pen Argyl, PA - derailed tender, L&NE and wooden hopper #419
881	05/06/11	Fire screen of locomotive in smokebox
939	07/06/11	Philadelphia and Reading Co. #25831 - drop end "Fishbelly" Gondola - end open
940	07/06/11	Philadelphia and Reading Co. #25831 - drop end "Fishbelly" Gondola - end open
941	07/06/11	Philadelphia and Reading Co. #25831 - drop end "Fishbelly" Gondola - end open
942	07/06/11	Philadelphia and Reading Co. #25831 - drop end "Fishbelly" Gondola - end closed
943	07/06/11	Philadelphia and Reading Co. #25831 - drop end "Fishbelly" Gondola - end closed
944	07/06/11	Philadelphia and Reading Co. #25831 - drop end "Fishbelly" Gondola - end closed, coupler and beam
945	07/06/11	Philadelphia and Reading Co. #25831 - drop end "Fishbelly" Gondola - tightening hand brake
946	07/06/11	Philadelphia and Reading Co. #25831 - drop end "Fishbelly" Gondola - tightening hand brake
947	07/11/11	Locomotive cab - interior - engineer's side - camelback
956	07/27/11	NYC&HR RR car #56685 - box car - close clearance siding

<b>Neg. No.</b>	<b>Date</b>	<b>Description</b>
967	08/10/11	Car #46191 - Gondola (RR?) - pulled drawhead
968	08/10/11	Car #46364 - Gondola (RR?) - pulled drawhead
985	10/27/11	Road crossing - Hanover Branch (H 1682) - view of railroad with loco
986	10/27/11	Road crossing - Hanover Branch (H 1682) - view of railroad with loco
1052	02/24/12	Hopper car - view of coupler and end sill - DL&W #73181
1053	02/24/12	Hopper car - end view
1054	02/24/12	Hopper car - view of damaged coupler plate
1055	02/24/12	Hopper car - end view - damaged area
1056	02/24/12	Brake wheel with brake lever bar in place
1063	03/10/12	Locomotive #584 - 1/2 view
1064	03/10/12	Locomotive #584 - front view
1065	03/10/12	Locomotive #584 - front and left side
1066	03/10/12	Locomotive #584 - end of pilot beam
1140	06/04/12	Locomotive #60 - Smokebox and fire screen
1146	07/23/12	Locomotive #780 - Close clearances with building at roundhouse lead
1147	07/23/12	Locomotive #780 - Close clearances with building at roundhouse lead
1148	07/23/12	Locomotive #780 - Close clearances with building at roundhouse lead
1149	07/23/12	Locomotive #780 - Close clearances with building at roundhouse lead
1150	07/23/12	Locomotive #780 - Close clearances with building at roundhouse lead
1159	08/14/12	Locomotive #742 - smokebox interior and fire screen
1173	08/21/12	Plymouth, PA - accident to ice wagon at station road crossing
1174	08/21/12	Plymouth, PA - accident to ice wagon at station road crossing
1175	08/21/12	Plymouth, PA - accident to ice wagon at station road crossing
1176	08/21/12	Plymouth, PA - accident to ice wagon at station road crossing
1177	08/21/12	Plymouth, PA - accident to ice wagon at station road crossing
1178	08/21/12	Plymouth, PA - accident to ice wagon at station road crossing
1179	08/21/12	Plymouth, PA - accident to ice wagon at station road crossing
1180	08/21/12	Plymouth, PA - accident to ice wagon at station road crossing
1197	10/18/12	Locomotive #535 - smokebox interior and fire screen
1197A	10/21/12	Branch line - country road crossing - accident scene
1198	10/21/12	Branch line - country road crossing - accident scene
1199	10/21/12	Branch line - country road crossing - accident scene
1200	10/21/12	Branch line - country road crossing - accident scene
1201	10/21/12	Branch line - country road crossing - accident scene
1202	10/21/12	Branch line - country road crossing - accident scene
1203	10/21/12	Branch line - country road crossing - accident scene
1204	10/21/12	Branch line - country road crossing - accident scene
1205	10/21/12	Branch line - country road crossing - auto involved in accident
1226	10/31/12	Locomotive #766 - clearance with refrigerator car opened door
1227	10/31/12	Locomotive #766 - clearance with refrigerator car opened door

**SECTION F - 11 X 14**

<b>Neg. No.</b>	<b>Date</b>	<b>Description</b>
009		Locomotive #1052, 4-6-0 Camelback (1/2 view)
218		Passenger train approaching on new double tracked straight "Pequest fill" - view from overpass
219		Passenger train receding on new double tracked straight "Pequest fill" - view from overpass
223		Tunkhannock viaduct - completed - first train (?) - locomotive and caboose
262		Ferry boat - "Scranton" - (side view)
263		Ferry boat - "Binghamton" - (side view)
264		Ferry boat - "Scandinavia" - (side view)
265		Ferry boat - interior - upper deck
266		Ferry boat - interior - lower deck
267		Engine #974 (4-4-0C) with passenger train (6 passenger cars) at signal (posed)
268		Engine #1101 - (1st of the DL&W Pacifics) side view
270		"Phoebe Snow" on running board step - engine #974 (4-4-0C)
271		"Phoebe Snow" on running board step - engine #969 at Water Gap station
272		"Phoebe Snow" - in locomotive cab - camelback - engine #969 at Water Gap station
273		"Phoebe Snow" - on observation platform - with photographers
276		Copy of drawing of "Spitfire"